

# **HF HYDRO-FORCE**

**Accessories for the Carpet Cleaning Professional**

**SUBJECT:** Unloader change

**EFFECTIVITY DATE:**

July 2012

The PT019 Unloader used on the Olympus M1200 is being discontinued and replaced with the PT016 Unloader

**Old PT019**



**New PT016**



Old P/N	New P/N	Description
PT019	PT016	1200 psi Unloader
PT019A	PT016A	Unloader Repair Kit

**SUMMARY:**

**The new PT016 has the following feature and improvements:**

- Forging is 24% stronger.
- Easy grip unloader knob.
- The bypass port is increased from 1/4" to 3/8" NPT to help reduce bypass pressure at higher flow rates – up to 8 GPM.
- The PT016 unloader was endurance tested for 50,000 cycles.

The springs from the PT019 are interchangeable with the PT016 . However, none of the other parts are interchangeable. Also, there is a yellow plastic part that needs to be removed with a screwdriver in order to spin the knob off the unloader.